

SERVICE DEPARTMENT 2019 COMMON PARTS LIST



This list does not include all parts, only the most commonly requested ones. If you do not see a part on this list, please contact the Service department at +1 503.641.7287 for more information.

Prices and parts availability are subject to change without prior notice.
Prix et composants sujets à modification sans préavis.

AUDIA® / NEXIA® PARTS

Description	Biamp Part Number	Price (USD)	Notes
120V power cord for power supplies	330.0002.900	\$6.60 ea.	
Alps power supply	703.0549.900	\$73.25 ea.	for all Nexia units
Audia PA-2 internal harness	650.0278.90B	\$35.34 ea.	
Audia TI-2 label	549.0107.90B	\$1.56 ea.	
Audia VoIP-2 cable	330.0040.900	\$73.98 ea.	
Audia VoIP-2 label	549.0142.90B	\$3.84 ea.	
AudiaEXPI/EXPO 24 VDC supply	725.0001.900	\$46.20 ea.	
AudiaEXPI/EXPO fan	521.0003.90A	\$13.29 ea.	
AudiaFLEX CM fan	521.0002.90A	\$26.67 ea.	units built from 2003 - 09/12
AudiaFLEX CM fan	521.0009.90B	\$15.93 ea.	for units built after 10/12
AudiaFLEX CM-1J (module only)	703.0647.90C	\$590.00 ea.	
AudiaFLEX CM-1J assembly	752.0003.90H	\$696.00 ea.	for units built after 07/13
AudiaFLEX CM-1J assy w/ install	752.0003.90E	\$896.00 ea.	
AudiaFLEX chassis fan	521.0008.90B	\$15.93 ea.	for units built after 04/12
AudiaFLEX chassis fan	521.0001.90B	\$26.67 ea.	units built from 01/08 - 03/12
AudiaFLEX chassis fan	521.0001.90A	\$26.67 ea.	units built from 2003 to 2007
AudiaFLEX filler plate screws	525.0120.900	\$0.10 ea.	need 2 per filler plate
AudiaFLEX filler plates	551.0819.90A	\$0.52 ea.	
AudiaFUSION, VA-8600 fan	520.0191.90E	\$23.94 ea.	2 fans are in each unit
AudiaSOLO, Nexia fan	521.0004.90E	\$14.34 ea.	for units built after 11/07
AudiaSOLO, Nexia fan	521.0004.90A	\$14.55 ea.	units built from 07/05 - 10/07
AudiaSOLO, Nexia fan	521.0003.90A	\$13.29 ea.	units built from 01/04 - 06/05
Biamp badge	368.0021.90B	\$5.68 ea.	
Cosel power supply	370.0001.900	\$181.33 ea.	for FLEX built after 02/07
EOS power supply*	704.0001.90A	\$132.60 ea.	for all SOLOs, pre-02/08 FLEX

* To install an EOS power supply in an older Nedap equipped unit (manufactured prior to June 2004), additional parts will be required (\$14.00). Please contact the Service department at +1 503.641.7287 for details.

TESIRA® PARTS

Description	Biamp Part Number	Price (USD)	Notes
I/O card filler plate	548.0117.90E	\$2.04 ea.	
Filler plate screw	525.0120.900	\$0.10 ea.	need 1 per filler plate

CONNECTORS

Description	Biamp Part Number	Price (USD)	Notes
2-pin (Yellow) [FUSION/VA-8600]	520.0188.900	\$6.00 ea.	no strain relief
3-pin (Black)	520.0123.900	\$6.00 ea.	no strain relief
4-pin (Black)	520.0128.900	\$2.92 ea.	no strain relief
5-pin (Black)	520.0138.900	\$3.16 ea.	no strain relief
Audia 3-pin (Yellow)	520.0176.900	\$3.68 ea.	w/ strain relief
Audia 4-pin mini (Green) [TI-2]	520.0160.900	\$5.88 ea.	w/ strain relief
Audia and Vocia 3-pin (Black)	520.0162.900	\$3.28 ea.	w/ strain relief
Audia and Vocia 3-pin (Green)	520.0164.900	\$3.28 ea.	w/ strain relief
Audia and Vocia 3-pin (Orange)	520.0163.900	\$3.28 ea.	w/ strain relief
Audia and Vocia 5-pin (Black)	520.0165.900	\$5.80 ea.	w/ strain relief
Audia and Vocia 5-pin (Green)	520.0186.900	\$7.28 ea.	w/ strain relief
Audia and Vocia 6-pin mini (Black)	322.0389.900	\$8.28 ea.	w/ strain relief
autoTWO 3-pin	520.0180.900	\$3.36 ea.	no strain relief
autoTWO 4-pin	520.0182.900	\$4.48 ea.	no strain relief
Tesira 3-pin (Black)	322.0394.900	\$3.52 ea.	w/ strain relief and silkscreen
Tesira 3-pin (Blue)	322.0395.900	\$3.52 ea.	w/ strain relief and silkscreen
Tesira 3-pin (Green)	322.0393.900	\$3.52 ea.	w/ strain relief and silkscreen
Tesira 3-pin (Orange)	322.0392.900	\$3.52 ea.	w/ strain relief and silkscreen
Tesira 5-pin	520.0138.900	\$3.16 ea.	w/ strain relief and silkscreen
Tesira 6-pin (Green)	322.0388.900	\$8.28 ea.	w/ strain relief and silkscreen
Tesira and Vocia 6-pin (Black)	322.0381.900	\$7.80 ea.	w/ strain relief
Vocia 2-pin (Black)	322.0128.900	\$2.80 ea.	w/ strain relief
Vocia 4-pin (Black)	322.0390.900	\$5.72 ea.	w/ strain relief
Vocia 4-pin (Yellow)	520.0004.900	\$7.84 ea.	w/ strain relief
VS8/V8 (2006 model)	520.0156.900	\$3.76 ea.	no strain relief
VS8/V8 (2007 and after)	520.0173.900	\$3.88 ea.	no strain relief

WALL WART/LINE LUMP PARTS

Description	Biamp Part Number	Price (USD)	Notes
301/601/801 etc. (24 VDC)	725.0001.900	\$46.20 ea.	
Vocia POTS-1/VI-8/VOIP-1 (24 VDC)	283.0119.900	\$50.58 ea.	
120V power cord for above	330.0002.900	\$6.60 ea.	

MISCELLANEOUS PARTS

Description	Biamp Part Number	Price (USD)	Notes
CPA650 capacitors (70V out)	245.0007.900	\$6.84 ea.	
DS-4/10 gooseneck mic	449.0003.91A	\$50.38 ea.	
Label sheets	549.0105.90A	\$11.56 ea.	
MXA/MPA light pipes	340.0036.900	\$0.76 ea.	
NPS-1 gooseneck mic	449.0002.900	\$110.25 ea.	
NPS-1 wheel	360.0048.90A	\$7.88 ea.	
RED-1 grey base	368.0051.90B	\$8.48 ea.	
RED-1F mounting plate	551.0101.90A	\$10.96 ea.	
RED-1F screws	525.0258.900	\$0.32 ea.	4 required per unit
RED-1F trim plate	368.0053.90D	\$9.28 ea.	
RP-L1 pot (25K)	170.0001.900	\$2.72 ea.	
V8/VS8/S8 knob	360.0046.900	\$5.52 ea.	
WS-4/10 replacement mic	Contact the Orders Department for price and availability		

SHIPPING AND HANDLING RATES¹

A \$5.00 handling fee will be applied to each billed parts order.

A \$12.90 fee will be applied to each COD shipment.

Shipping charges for the continental US (if weight is less than 2 lbs.) are as follows:

FedEx Ground: \$8.95

FedEx Express: \$16.00

FedEx 2 Day: \$20.50

FedEx P1: \$38.00 (ask for EARLY AM² quote)

¹ International parts orders have no set shipping rates. These orders will be billed the exact shipping charges.

² International orders and early AM shipments require phone numbers.